



## Volkswagen Passat

VIN-код: WVWZZZ3CZKE133232

Дизельне паливо

2019

Згенеровано 18.03.2025, 16:23



### Тип

✓ Виглядає нормально



### Одометр

✓ Виглядає нормально



### Юридичний статус

✓ Виглядає нормально



### Пошкодження

✓ Виглядає нормально



+31

### Джерела даних

Ми перевірили 900+ джерел даних у 35 країнах

## Тип

Транспортний засіб застосовувався як таксі, прокатний чи інший службовий ТЗ? Примітка: такі ТЗ можуть бути в гіршому стані, ніж зазвичай!



### Проблем не знайдено

Немає записів про використання ТЗ нестандартним чином

## Результати перевірки:



Таксі

✓ Записи не знайдені

Немає доказів використання як таксі



Перевезення

✓ Записи не знайдені

Немає доказів використання як ТЗ для перевезень



Прокатний

✓ Записи не знайдені

Немає доказів використання як прокатного ТЗ



Поліція

✓ Записи не знайдені

Немає доказів використання поліцією



Демонстраційний

✓ Записи не знайдені

Немає доказів використання як демонстраційного транспортного засобу




ТЗ школи водіння

✓ Записи не знайдені


Немає доказів використання як ТЗ в школі водіння


## Викрадення

Транспортний засіб наразі позначений як викрадений? Викрадався в минулому? Був знайдений?

 **Проблем не знайдено**

Ми не знайшли записів про викрадення транспортного засобу.

 **Примітка**

Перевірку по поліцейській базі даних про викрадені автомобілі виконано в **9 країнах**:  +3

### Ось що ми перевірили:



**Наразі розшукується як викрадений**  Записи не знайдені



**Викрадений в минулому**  Записи не знайдені Поточний статус невідомий




**Викрадений в минулому**  Записи не знайдені Транспортний засіб був знайдений

### База даних поліції щодо викрадених транспортних засобів, перевірку завершено:

 Данія

 Чехія

 Словенія

 Румунія

 Італія

 Словаччина

 Угорщина

 Швеція


 Канада

## Одометр

Чи є ознаки скручування або розбіжності пробігу?

 **Примітка**

- Останній відомий пробіг: 59 968 км
- Середній пробіг для аналогічних моделей: 151 639 км
- Знайдено записів пробігу: 2



#### Дані одометра

08.2019	13 км
08.2021	59 968 км

## Юридичний статус

Транспортний засіб пройшов техогляд? Чи має відмітку про здачу в утиль?

- ✓ Проблем не знайдено  
Дані про юридичний статус транспортного засобу не знайдені

### Юридичні

✓= Техогляд ✓ Записи не знайдені Записи про техогляд не знайдені


↻ Брухт ✓ Записи не знайдені Немає запису про позначення транспортного засобу як утилізованого

## Пошкодження

Транспортний засіб мав пошкодження в минулому? Вартість пошкоджень?

- ✓ Проблем не знайдено

## Записи про пошкодження



Можливі окремі неточності, особливо під час перевірки старих транспортних засобів. Підпільні ремонтні майстерні можуть незаконно приховувати дефекти чи пошкодження, ніде не фіксуючи їх наявність. Часом можлива навіть підміна VIN-номерів. У нас є різні методи виявлення таких порушень, але 100% гарантію дати неможливо.

## Стихійні лиха

Чи зафіксовано місцезнаходження транспортного засобу в зоні стихійного лиха?

- ✓ Проблем не знайдено  
Даних про перебування цього транспортного засобу в зоні стихійного лиха не зафіксовано

## Ринкова вартість

За яку суму ТЗ був проданий у минулому? Яка середня ціна ТЗ цього року випуску і моделі?

- і Примітка
  - Середня ринкова ціна на такий ТЗ: 20 806 USD
  - Остерігайтесь прихованих проблем, якщо ТЗ продавався за ціною значно нижчою за поточну!

## Поточна ринкова вартість Volkswagen Passat 2019

Ринкова вартість визначається шляхом дослідження ціни конкретної моделі автомобіля (виробленого в тому ж році) у країні, де було створено звіт. Ми аналізуємо дані за останні 6 місяців.

Найнижча ціна

18 650 USD

Середня ціна

20 806 USD

Найвища ціна

23 353 USD

## Специфікації та обладнання

Які специфікації та яке обладнання зареєстровані для цього транспортного засобу?



#### Примітка

Перевірте, чи специфікації та комплектація транспортного засобу відповідають фактам, зазначеним продавцем.

## Ідентифікаційний код і технічні характеристики



Марка

**Volkswagen**



Модель

**Passat**



Тип кузова

**Вантажопасажирський**



Рік виробництва

**2019**



Об'єм силового агрегата

**2 л**



Потужність силового агрегата

**110 кВт (148 к. с.)**



Тип палива

**Дизельне паливо**



Тип трансмісії

**Автоматична**



Тип приводу

**Передній привід**



Розміщення керма

**Лівостороннє керування**



Кількість циліндрів

**4**



Код двигуна

**DFGA**

## Обладнання

Як отримано від виробника

0B4

WHEELBASE

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0NA

WITHOUT NAMEPLATE SET (WITHOUT MODEL DESIGNATION)

0RE

WITHOUT ELECTRONIC STEERING COLUMN LOCK

0TD

FLOOR MATS IN FRONT AND REAR

0Y1

STANDARD CLIMATIC ZONES

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1KU

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1Q2

MASS DAMPER FOR STEERING WHEEL, 36 HZ

1SB

ADDITIONAL FRONT UNDERBODY GUARD

1X0

FRONT WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

20A

WITHOUT ELECTRIC MOTOR ( HYBRID )

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2JL

COMFORT BUMPERS

0IJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0M4

FUEL TANK

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0SB

LABELS/PLATES IN GERMAN

0VE

INFORMATION KIT IN FLEMISH/FRENCH

0YF

WEIGHT RANGE 6 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1G3

ALLOY SPARE WHEEL WITH ORIGINAL EQUIPMENT TIRES

1M6

TRAILER HITCH MECHANICALLY SWIVELING AND POWER-DETACHABLE

1PF

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1Y0

WITHOUT DIFFERENTIAL LOCK

1ZA

DISK BRAKES IN FRONT

2A0

WITHOUT DELIVERY EQUIPMENT

2H0

WITHOUT "DRIVE SELECT"

2P2

STAINLESS STEEL LOADING EDGE PROTECTION

2WA

WITHOUT ADDITIONAL TIRES

31K

FRONT AND REAR LICENSE PLATE CARRIER (ECE)

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3D3

CENTER CONSOLE

3GN

VARIABLE CARGO AREA

3NT

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING (THREE PIECES) WITH CENTER ARMREST

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3T2

THREE REAR HEAD RESTRAINTS

3Y4

ROLL-UP SUNSHADE FOR REAR SIDE WINDOWS

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4B4

PROTECTIVE SIDE MOLDING

4E2

TAILGATE/TRUNK LID RELEASE FROM INSIDE (ELECTRICALLY)

4H3

MANUAL CHILD SAFETY LOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4M6

BEVERAGE HOLDERS

2ZD

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL WITH TIPTRONIC, HEATED

3A0

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM I-SIZE, 2X TOP TETHER

3CX

NET PARTITION

3FU

BIG ROOF SYSTEM

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3PW

MAN. HEIGHT ADJUSTM. F. FRONT SEATS AND SEAT CUSHION TILT AND DEPTH ADJUST. LEFTPLUS ELECTRIC BACKREST ADJUSTM. LEFT

3S1

BRIGHT ROOF RAILS

3U2

SLIDING TRUNK COVER

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4AN

DOOR AND SIDE TRIM PANEL

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4GW

HEAT INSULATING WINDSHIELD

4I7

CENTRAL LOCKING SYSTEM "KEYLESS-GO" WITHOUT SAFELOCK

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4UN

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION, INCLUDING KNEE AIRBAG ON DRIVER SIDE

4V0

WITHOUT FRONT PASSENGER SEAT CONTROL

4ZB

BRIGHT MOLDINGS

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5XV

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

6A0

WITHOUT FIRE EXTINGUISHER

6K4

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "HIGH"

6NA

UNSPLIT MOLDED HEADLINER

6SM

LUGGAGE COMPARTMENT FLOOR COVERING IN NEEDLE-PUNCHED NONWOVEN (DILOURS)

6XI

EXT. MIRR., AUTO-DIMMING, ELECTR. FOLD./ADJUSTABLE, HEATED, W/ FRONT PASSENGER EXTERIOR MIRROR LOWERING FUNCTION

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7M1

SCUFF PLATES IN DOOR APERTURES WITH METAL CORES

4X4

SIDE AIRBAG IN FRONT AND REAR WITH CURTAIN AIRBAG

5C0

WITHOUT SPECIAL BODY MEASURES

5J0

WITHOUT REAR SPOILER

5MD

DECORATIVE ALUMINUM INSERTS

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5ZC

HEAD RESTRAINTS FOR FRONT SEATS (X-ADJUSTMENT)

6E3

CENTER ARMREST IN FRONT

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T1

INTERIOR LIGHT IN FOOTWELL

79D

LANE CHANGE ASSIST, LANE KEEPING SYSTEM, TRAFFIC JAM ASSIST, AND EMERGENCY ASSIST

7B3

12-VOLT SOCKET(S)

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7P7

POWER-ADJUSTABLE LUMBAR SUPPORT FOR LEFTFRONT SEAT

7RE

SD CARD (EUROPE)

7UF

NAVIGATION SYSTEM - STANDARD

7X5

PARK ASSIST

8FA

WITHOUT SECOND BATTERY

8GV

ALTERNATOR 180 A

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8S6

2 READING LIGHTS IN FRONT

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8WH

FRONT FOG LAMP AND CORNERING LAMP

8Y1

TWO-TONE HORN

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9F0

WITHOUT SOUND COMBINATION FOR ROTATING EMERGENCY LIGHT AND RADIO ANTENNA PREPARATION

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9S8

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"FPK" (ACTIVE INFO DISPLAY)

9TJ

7U0

STANDARD ENGINE STARTER

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7ZD

VEHICLE CLASS DIFFERENTIATION -3G0-

8G3

ADVANCED HIGH-BEAM CONTROL

8IU

LED HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8RM

8 SPEAKERS (PASSIVE)

8SP

LED TAIL LAMP ASSEMBLY

8TB

REAR FOG LAMP

8X1

HEADLAMP WASHER SYSTEM

8Z5

NOT HOT COUNTRY

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9JA

NON-SMOKER'S PACKAGE

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9T1

HEATED WASHER NOZZLES IN FRONT

9WV

ADDITIONAL LED WARNING LIGHT (DOOR AREA)IN  
FRONT

9Z0

OPERATING VOLTAGE 12 V

A60

CATEGORY 0

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-  
SPECIFIC BUILDING REGULATION

DN4

4-CYL. TURBO DIESEL ENGINE 2.0 L/110 KW (4V) TDI  
COMMON RAIL; B.ENGINE T37/T6F  
TS1/TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I

EA0

WITHOUT FOLLOW-ON WARRANTY

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD  
UNITCODING, WITHOUT ENGINE IMMOBILIZER  
INTERCONNECTION

ER1

REGIONAL CODE " ECE " FOR RADIO

EV0

WITHOUT CHARGING CABLE

F94

ALLOY WHEELS 7J X 17

FM0

BASIC EQUIPMENT VARIANT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

I8F

STANDARD RADIO (GEN2 GP)

K8D

WAGON/AVANT

WIRELESS RSE "APP"

9ZE

COMFORT TELEPHONE SYSTEM

A8F

SPORTS EQUIPMENT

B02

TYPE APPROVAL COUNTRY BELGIUM

C56

OPERATING PERMIT, ALTERATION

E0A

NO SPECIAL EDITION

EFO

WITHOUT ECO FUNCTION

EM1

DRIVER ALERT SYSTEM

ES0

WITHOUT VEHICLE INLET

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD  
EQUIPMENT

FC0

WITHOUT CUSTOMIZED INSTALLATION

G03

SHOCK ABSORPTION IN FRONT

GM1

STANDARD ELECTRONIC ENGINE SOUND

H5R

TIRES 215/55 R17 94V SUPER-LOW ROLLING  
RESISTANCE (POLYMER COATING)

J0V

BATTERY 420 A (70 AH)

KA6

WITH FRONT AND REAR VIEW CAMERA SYSTEM AND  
TWO SIDE CAMERAS

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR  
CONDITIONING CONTROL PANEL

KS0

WITHOUT HEAD-UP DISPLAY

L22

SUSPENSION RANGE 22 INSTALLATION CONTROL  
ONLY, NO REQUIREMENT FORECAST

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

Q4H

SPORTS COMFORT SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS ( VARIABLE )

QK1

WITH MULTIFUNCTION CAMERA

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

TR1

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 04L.A

UC7

REAR SHOCK ABSORPTION, SUSPENSION WITH  
INCREASED RIDE HEIGHT

UH2

PARKING BRAKE

UP0

ANALOG CLOCK

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR  
OPENER

VL3

EXTENDED AND PROACTIVE PEDESTRIAN  
PROTECTION

KK3

REFRIGERANT R1234YF

LOL

LEFT-HAND DRIVE

N7K

SEAT TRIM COVERS IN ALCANTARA/LEATHER

NZ4

PRIVATE EMERGENCY CALL SYSTEM

QA0

WITHOUT CHILD SEAT

QH0

WITHOUT VOICE CONTROL

QJ3

CHROME PACKAGE (TYPE 2)

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QV3

DIGITAL RADIO RECEPTION

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG6

HILL START ASSIST

UI2

ELECTRIC INTERFACE FOR EXTERNAL USE AUX-IN  
JACK AND 2 X USB

VOF

CONTINENTAL TIRES

VF0

STANDARD PEDAL CLUSTER

X2A

EQUIPMENT OPTIONS SUBSET FOR BELGIUM

## Хронологія

Знайдено 1 запис

## Останні записи

08.2019  Країна невідома



**Був виготовлений**

Країна (або штат) указує місцезнаходження заводу-виробника, складального підприємства або адресу реєстрації виробника. Дата може бути приблизною.



+31

**Джерела даних**

Ми перевірили 900+ джерел даних у **35 країнах**